


## Stop Static Usage Guide



1. Tie one end of the static string to one of the magnets and attach that magnet to one side of the inner wall of the vinyl cutter on the back side.



2. Drape the string so that it makes plenty of contact with the vinyl surface, but doesn't have enough slack to be pulled under the pinch rollers when cutting vinyl.



3. Once the proper length has been selected tie off the end to the second magnet and affix that magnet to the inner wall of the vinyl cutter



4. The application is now complete and should look something like this

*\*If static problems continue then attach a grounding wire to a screw on the bottom of the machine and the other end to a screw on the stand of your vinyl cutter (or some other ground).\**


## Stop Static Usage Guide



1. Tie one end of the static string to one of the magnets and attach that magnet to one side of the inner wall of the vinyl cutter on the back side.



2. Drape the string so that it makes plenty of contact with the vinyl surface, but doesn't have enough slack to be pulled under the pinch rollers when cutting vinyl.



3. Once the proper length has been selected tie off the end to the second magnet and affix that magnet to the inner wall of the vinyl cutter



4. The application is now complete and should look something like this

*\*If static problems continue then attach a grounding wire to a screw on the bottom of the machine and the other end to a screw on the stand of your vinyl cutter (or some other ground).\**