


PORTABLE WORKING TABLE ASSEMBLY




Completed Table



Connectors



Included Tool



STEP 1:

Insert a connector piece into the end of one of the crossbeam sections.



STEP 2:

Make sure that the connector piece is inserted all of the way. You will be able to see the screw head on the connector piece through the hole on the crossbeam.



STEP 3:

Slide the crossbeam section with the connector piece into one of the slots in the center of one of the leg sections.



STEP 4:

Use the included tool to set the connector in place. Make sure that you use enough pressure that the crossbeam does not move.

STEP 5:

Repeat steps 1-4 for each crossbeam end until table is assembled (as shown above)