



DTF Heat Press Application Setting

Cotton/Blends

Set heat press to 315°F and high pressure

Press for 15 seconds, peel while hot

Press a second time with a Finishing Sheet

Poly/Triblends

Set heat press to 270°F and medium pressure

Press for 10 seconds with heat pillow, peel while hot

Press a second time with Finishing Sheet for 5 seconds